GIS REGISTRY INFORMATION

SITE NAME:	Shell Oil Co-F	PEV			
BRRTS #:	03-41-002073	3		FID#	
				(if appropriate):	
COMMERCE #	53209-5326-0	00		,	
(if appropriate):					
CLOSURE DATE:	January 7, 20				
STREET ADDRESS: CITY:	3800 W Ham	pton			
	Milwaukee		<u> </u>		
SOURCE PROPERTY		DINATES	X = 685967	$ \mathbf{Y} = 294 $	4479
(meters in WTM91 pro					
		Groundwater		Soil Both	X X
OFF-SOURCE GW CO		JN >ES:	Yes	No	Х
• IF YES, STREET A					
 GPS COORDINAT 		(=		Y =	
(meters in WTM91 pro			ri		
OFF-SOURCE SOIL O			Yes	No X	
Generic or Site-SpeIF YES, STREET A		HCL):			
 GPS COORDINAT 		X =			
(meters in WTM91 pro	l.	^ =		Y =	
CONTAMINATION IN		AY: Yes X		No	
<u></u>			S NEEDED		
Closure Letter, and any con	ditional closure le				
Copy of most recent deed, in			tod proportion		X
					<u>X</u>
Certified survey map or rele				legal description) for all affec	ted properties
County Parcel ID number, if	used for county,	for all affected prope	rties		Х
Location Map which outlines a	Ill properties within co	ontaminated site boundar	ies on USGS topogra	phic map or plat map in sufficien	t detail to permit the X
parcels to be located easily (8.5x potable wells within 1200' of the s	14" if paper copy). If	groundwater standards	are exceeded, the ma	ap must also include the location	of all municipal and
Detailed Site Map(s) for all		es. showing buildings	 roads_property_bound	daries contaminant sources util	ity lines monitoring V
wells and potable wells. (8.5x14"	, if paper copy) This	map shall also show the	location of all contan	ninated public streets, highway ar	nd railroad rights-of-
way in relation to the source prop exceeding ch. NR 720 generic or	SSRCLs.	o the boundaries of grou	ndwater contaminatio	n exceeding ch. NR 140 ESs and	d soil contamination
Tables of Latest Groundwat	er Analytical Resu	ılts (no shading or c	oss-hatching)		х
Tables of Latest Soil Analyti	cal Results (no si	ading or cross-bate	hing)	* 1 mm 1 mm 1 mm 2 mm 2 mm 2 mm 2 mm 1 mm	
Isoconcentration map(s), if					<u>X</u>
and extent of groundwater contain	nination defined. If no	it available, include the	latest extent of cont	rne isoconcentration map snould a <mark>minant plume map.</mark>	nave flow direction X
OW. Table of make land along					
GW: Table of water level ele				· 	
GW: Latest groundwater flo is greater than 20 degrees)	w direction/moni	toring well location r	nap (should be 2 i	maps if maximum variation	in flow direction X
SOIL: Latest horizontal exte	ent of contaminati	on exceeding generi	c or SSRCLs, with	one contour	X
Geologic cross-sections, if i					x x
					 ^
RP certified statement that I			curate		
Copies of off-source notification	ation letters (if app	olicable)		- · · · · · · · · · · · · · · · · · · ·	
Letter informing ROW owne	r of residual conta	amination (if applical	ne)(public highway	or railroad ROW)	
Copy of (soil or land use) de				,	X
oopy or (soil or land use) de	ea restriction(8) (n deed notice ii any	requireu as a con	uiuon oi ciosure	

101 West Pleasant Street, Suite 100A Milwaukee, Wisconsin 53212-3963

TDD #: (608) 264-8777 Fax #: (414) 220-5374

http://www.commerce.state.wi.us http://www.wisconsin.gov James E. Doyle, Governor



January 7, 2003

Mr. Jeff Johnson ExxonMobil Refining and Supply Company P.O. Box 874 Joliet, IL 60434

RE: Final Closure

Commerce # 53209-5326-00 WDNR BRRTS # 03-41-002073 Shell Oil Co-PEV (former), 3800 West Hampton Avenue, Milwaukee

Three 12,000-gallon unleaded gasoline underground storage tanks (USTs) in use; one leaded and three unleaded gasoline USTs removed in 1988; one waste oil UST abandoned without product in 1980; one fuel oil UST abandoned without product in 1985

Dear Mr. Johnson:

The Wisconsin Department of Commerce (Commerce) has received all items required for closure of the site referenced above. This site is now listed as "closed" on the Commerce database and will be included on the Wisconsin Department of Natural Resources (WDNR) Geographic Information System (GIS) Registry of Closed Remediation Sites to address residual soil and groundwater contamination.

It is in your best interest to keep all documentation related to the environmental activities at your site. If residual contamination is encountered in the future, appropriate measures must be implemented to assure that it is managed following all applicable regulations. If future site conditions indicate that any remaining contamination poses a threat, and subsequent information indicates a need to reopen this case, any original claim under the PECFA fund would also reopen and you may apply for assistance to the extent of remaining eligibility.

Thank you for your efforts to protect Wisconsin's environment. If you have any questions, please contact me in writing at the letterhead address or by telephone at (414) 220-5376.

Sincerely,

Linda M. Michalets Hydrogeologist Site Review Section

cc: Ms. Tammi Nagel, Handex of Wisconsin

Case file

REEL 3445 IMAG 855


WARRANTY DEED STATE OF WISCONSIN FORM 5

OS-PEV	7039450
This Indenture, Made this O'The day of DECEMBER	·
corporation switch corporation, a New York	RESISTER'S OFFICE SEE SEE
Rashinder Lal and Harshinder P. Bhatia of the first part, and	DEC 2 8 1994
Witnesseth - part 1625 of the second part	1866
our of one dellar and other good and valuable consideration of the	OF DEEDS
to il	MASHINGA LANGE THE MASHER MASHER WILL STAIL
and State of Wisconsin, towar,	-
Legal Description Attached	
Party of the first part hereby retains Repurchase Rights Refusal as set forth on <u>Exhibit</u> A attached hereto. Parti by acceptance of this Deed hereby grant such Repurchase R First Refusal to party of the first part.	instruction of the instruction of the contract
Tax Key No. 208-0602-210-2	RECORD 16.00 RIX 491.70
TRANSFER	
\$ 491.70 FEE	
AND CONTRACTOR OF THE CONTRACT	d appur enunces, unto the said part $\frac{1}{2} \frac{C_{1}}{C_{2}}$. R.
or 115 heirs, executors and administrators, do CS with the said part 10S of the second part their heirs and assignment peaceable possession of the said part 10S of the second part, their heirs and assignment peaceable possession of the said part 10S of the second part, their heirs and assignment the whole or any part thereof, by, through or under said Mobil Oll COPD	Givenant, prant, bargain and agree to and a, that the above bargained premises, in the except
In Witness Whereof and none other.	NT and DEFEND.
In Witness Whereof, the said part 2 of the first part 12.5 1	hereunto set
SIGNED AND STALLD IN PRESINCE OF BYEN	RECEALTION BLACKER ASSISTANT TERROLOGIC
Attest:	A. C. EVENDON-SE. ASST. SECRETARY
& adhim -	(SEA)
·	— (SEA)
STATE OF TECONOMY	
Personally came before me, this 6th day of DES c doing named. B.A. IATULNA - ASSISTANT THEASURER P.A. STYLESON - SP. AST. SPONETARY	CEMEER A. Polito 94
me known to be the person S who executed the foregoing instrument and acknowledged the	water wines
HIS INSTRUMENT WAS CRAFTED BY ASSAULT	were wy an

Attorney Garago, T. Warzyn

Notary Public Commonwealth of Virginia

Lots 16, 17, 18, 19, 20, 21 and the East 15 feet of Lot 22, in Block 4, In North Milwaukee Plat No. 1, in the Southeast 1/4 of the Southwest 1/4 of Section 36, in Township 8 North, Range 21 East, in the City of Milwaukee, County of Milwaukee and State of Wisconsin, excepting therefrom that part which is bounded and described as follows: Commencing at the Southeast corner of said Lot 16, said Southeast corner being 33 feet North of the South line of said 1/4 Section; thence West 201.43 feet to a point in the South line of said Lot 22, said point lying 15.00 feet West of the Southeas' corner of said Lot 22; thence North and parallel to the East line of Lot 22 aforesaid, 12.00 feet to a point, said point lying 45.00 feet North of and measured at right angles to the South line of said 1/4 Section; thence East and parallel to the South line of said 1/4 Section 45.00 feet to a point in the East line of said Lot 21; thence Northeasterly 140.64 feet to a point in said Lot 16, said point lying 20.25 feet East of and measured at right angles to the West line of sald Lot 16, and 21.37 feet North of and measured at right angles to the South line of said Lot 16; thence Northeasterly 10.91 feet to a point in the Easterly line of said Lot 16, said point lying 33.32 feet Northwesterly of the Southeast corner of said Lot 16; thence Southeasterly along the Easterly line of Lot 16 aforesaid, 33.32 feet to the point of commencement.






TABLE 2 GROUNDWATER LABORATORY ANALYTICAL RESULTS Mobil Service Station 05-PEV Milwaukee, Wisconsin

	5				Ē		Total	
Well Number	Sampie Date	Benzene	Toluene	Ethyl- benzene	lotal Xylenes	MTBE	I rimethyl- benzenes	GRO
MW-1	01/14/1992	Ð.	ND	1.3	5.7	09		1
	05/18/1994	ND	QN	Q.	2.1	ND	3.9	
	12/07/1994	N N	R	QN	QN	Q.	Ð	1
-	03/31/1995	QN QN	9.	<u>N</u>	N N	8.1	<u>D</u>	ł
	96/06/1662	Q.	Ð	ND	ΩN	2.9	2.9	ļ
	08/30/1995	Ð.	Q.	QN	N ON	1.2	Q2	;
	06/02/1996	-	1	į	-		-	ļ
	12/03/1996	QN	Q.	P.	QN	NO	Ð	}
	2661/21/90	1	1	1	-	-		į
	12/15/1997	-		1	1	-		ļ
	11/24/1998	-	ļ	!		-	-	1
	02/25/1999			!	:	-	-	}
	05/26/1999	-		i	:		-	-
	08/05/1999	<0.10	<0.10	<0.25	<0.25	<0.25	<0.20	
A CASA	000171110	000						
7- M [N]	7661/41/10	200	55	200	910	750	-	-
	05/18/1994	460	Ð	360	470	180	432	ł
	12/07/1994	28	Q	1.2	Ð.	210	1.8	i
	03/31/1995	18	ND	57	Ð	83	20	!
	\$661/60/90	14	R	2	QN	120	QN.	!
	08/30/1995	ND	1.1	N ON	N	330	ON.	1
	06/02/1996	QN	9.	4	R	70	4	i
	12/03/1996	38	9	160	280	94	157	i
	2661/21/90	120	12	4	m	95	s	490
	12/15/1997	200	S	150	06	120	116	1500
	11/24/1998	190	'n	120	29	110	130	į
	02/25/1999	130	9.8	42	8.6	98	35	ļ
	05/26/1999	110	1.7	2.1	2.7	54	3.6	ļ
	DUP	110	1.6	2.2	2.4	52	3.6	ļ
	08/05/1999	95	0.39	1.0	1.7	99	1.2	-
NR 140 Standards								
ES		in !	1000	700	10000	09	480	N/A
PAL		0.5	200	140	1000	12	96	N/A

TABLE 2
GROUNDWATER LABORATORY ANALYTICAL RESULTS
Mobil Service Station 05-PEV
Milwaukee, Wisconsin

	GRO		ļ	-	1	į	1	}	ļ	120	140	;	-	!	-		ļ	1	į	-		i	ì	1	ļ	-	1		!		N/A N/A
Total	i rimetnyi- benzenes		QN ON	QN	R	ON.	ON.	ND	Q.	Q	QN.	<0.51	4.0	<1.02	<1.0		S	QN	ND	Ð	N.	-	Ð			0.34	1.0	2.9	<0.20		480 96
	MTBE	14	230	370	400	530	450	110	350	330	340	430J	100	96	200	130	F.8	1.2	1.7	R	ON ON		N ON		1	<0.53M	0.65	<0.16	<0.25		60
T. 2421	I otai Xylenes	5	S	Q.	Q	QN	ΩN	Q.	9	Ð	QN	<0.23	3.2	<0.46	<1.2	ND	S	ND	ND	N N	N		Q.	1	-	0.51	29.0	5.8	<0.25		10000 1000
Deberi	emyr- benzene	QN	Q.	Q.	Q.	R	R	Ð	£	ę.	Ð	<0.22	2.1	<0.44	<1.2	Q2	R	N N	QN	Ð.	J.		R			<0.22	0.78	1.2	<0.25		700 140
	Toluene		Q.	Ð	QN	Q	QN	Ð	N Q	Q.	Ð	<0.20	<1.0	<0.40	<0.50	QN	R	R	N N	Q	NU	i	Q.	i	-	<0.20	<0.20	0.92	<0.10		1000
	Benzene	ΩN	QN	6.1	R	R	2	2	S S	R	QN	<0.13	1.7	<0.26	<0.50	ND	ND	Q.	Q.	Ð	ŪN.	!	QN	:		<0.13	0.47	4.2	<0.10		5 0.5
Samula	Date	01/14/1992	05/18/1994	12/07/1994	03/31/1995	06/09/1995	08/30/1995	9661/50/90	12/03/1996	06/17/1997	12/15/1997	11/24/1998	02/25/1999	05/26/1999	08/02/1999	01/14/1992	05/18/1994	12/07/1994	03/31/1995	06/09/1995	08:30/1995	9661/50/90	12/03/1996	166/11/90	12/15/1997	11/24/1998	02/25/1999	05/26/1999	08/05/1999		
	Well Number	MW-3													. 08	MW-4								_						NR 140 Standards	

TABLE 2
GROUNDWATER LABORATORY ANALYTICAL RESULTS
Mobil Service Station 05-PEV
Milwaukee, Wisconsin

							Total	
Well Number	Sample Date	£	E	Ethyl-	Total	34700	Trimethyl-	Ç
Iadillas, ilas	Date	Benzene	Loluene	penzene	Xylenes	MIBE	penzenes	GKO
TF-3	01/14/1992	2200	1500	3000	9100	260		-
	05/18/1994	1200	QN	1200	1930	300	970	;
	DUP	1600	£	1400	2240	360	1140	ļ
	12/07/1994	570	4.5	250	102.6	340	191.7	1
	DUP	830	v	460	163.4	430	332.3	ļ
	03/31/1995	430	S	420	Q	610	380	į
	DUP	440	QN	480	Q.	029	400	
	06/09/1995	730	20	820	1210	1400	948	:
	DUP	710	17	790	1110	1500	898	;
	08/30/1995	250	11	53	54	1200	120	ł
	DUP	200	2.7	33	34	066	6.09	-
	06/02/1996	71	Q.	100	55	430	78	-
	DUP	46	Q	92	54	540	72	į
	12/03/1996	180	7	120	170	340	101	į
	DUP	190	∞	120	181	340	100	i
	16/11//9	180	m	13	28	130	10	1000
	DUP	250	4	17	36	230	13	1400
	12/15/1997	410	12	120	170	300	90	2700
	11/24/1998	280	6.9	350	140	170	124	ł
	DUP	300	7.4	370	140	190	124.3	ļ
	02/25/1999	740	5.8	067	84	170	78	į
	DUP	240	5.8	270	80	180	73	;
	05/26/1999	280	5.8	320	8	150	77	ļ
	6661/\$0/80	200	2.2	061	<1.2	73	4.6	!
	DUP	210	2.2	190	<1.2	88	4,4	!
NR 140 Standards								
ES		vo	1000	200	10000	09	480	N/A
PAL		0.5	200	140	1000	12	96	N/A
Notes: GRO - Gasoline Range Organics MTBE - Methyl Tert-Buryl Ether Parameter not analyzed Analytical results are reported in micrograms per liter (µg/L)			ES - Enforcement Standard PAL - Preventive Action Limit NA - No established ES or PAI	ES - Enforcement Standard PAL - Preventive Action Limit NA - No established ES or PAL		ND - Not detected J - Estimated concentration M - Matrix interference	ntration ence	
Total trineuty Denzenes equal the sum of 1,2		+-unmemyroenzene and 1,3,5-trimethyroenzene.	and 1,5,5-trime	inyibenzene.				

TABLE 1
SOIL LABORATORY ANALYTICAL RESULTS - VOLATILE ORGANICS

SERVICE STATION #05-PEV 3800 WEST HAMPTON AVENUE MILWAUKEE, WISCONSIN

	MTBE	(g) (ug/kg) (mg/kg)		-						!	-	16					QN			<25		<25 <10				<25 <10				
Total		(ug/kg) (mg/kg)	_			2.1 ND				ND ON						7.8						<75					_			
Ethyl-	41	(ug/kg) (t		QN	Ð.	1:1	ND			ND		1900								_		<25								
	Toluene	(ug/kg)	QN	ND	ON	1.0	QN	ON.	QN.	ND	2.2	110	3500	3900	14000	1.4	QN	3.6	<25	225	<25	<25	<25	<25	<25	<25	<25	<25	<25	
	Benzene	(ug/kg)	QN	ND ON	QN	2.6	QN	4.2	ΩN	ND	190	910	1100	770	3000	3.8	ON.	0.6	<25	527	<25	<25	<25	<25	<25	<25	<25	<25	<25	į
	Sample	Depth (ft)	5.0	30.0	5.0	5.0	5.0	5.0	5.0	20.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	5.0	3.0-5.0	3.0 5.0	13.0-15.0	3.0-5.0	12.0-14.0	3.0-5.0	12.0-15.0	5.0-7.0	3.0-5.0	12.0-14.0	3.0-5.0	0 4 0 6
	Sample	Date	12/18/1991		12/18/1991	12/19/1991	12/20/1991	12/19/1991	12/20/1991		12/19/1991	12/19/1991	12/18/1991	12/18/1991	12/18/1991	12/18/1991	12/18/1991	12/18/1991	08/29/1995	3661/08/80	08/29/1995	08/30/1995	08/29/1995	08/30/1995	08/29/1995	08/29/1995	08/30/1995	08/29/1995	08/30/1995	20011005100
	Soil Boring/	Well Number	MW-1		MW-2	MW-3	MW-4	TF-1	TF-2		TF-3	TF-4	PI-1	PI-2	PL-1	PL-2	PL-3	PL-4	SB-1	ςΒ <u>-2</u> ≜	SB-2	SB-3A	SB-3	SB-4A	SB-4	SB-5	SB-6A	SB-6	SB-7	000

SOIL LABORATORY ANALYTICAL RESULTS - VOLATILE ORGANICS TABLE 1


3800 WEST HAMPTON AVENUE SERVICE STATION #05-PEV MILWAUKEE, WISCONSIN


Soil Doning			_		Ethyl-	Total			
Well Number	Sample	Sample Denth (ft)	Benzene	Toluene	benzene	Xylenes	TPH	MTBE	GRO
		(III) IIIdəci	(ug/kg)	(ug/kg)	(ng/kg)	(ug/kg)	(mg/kg)	(119/kg)	(mo/ka)
SB-10	08/30/1005	3050	0.07	ÿ			io o	(66)	(911.9)
; ; ; ; ;		0.0-0.0	C7>	<25	\\ _25	<75	į	300	/10
SB-10		12.0-14.0	30/	307				7,7	710
1 40		0.11-0.21	77	675	3	<75	-	S	<10
71-gs	200 / C X	30-40	30/	000	ľ			62	217
: 45	,	0.0	67	57	\$5	<75		30>	710
SB-11		12.0-14.0	30/	200				72	AI.
		0.11.0.21		57	\$7>	<75	-	36	110
HA-	06/02/1666	ر د	300	30/	,			67	ΔĪ/
114.3			77	37	57		-	\$0	<10
7-YH	06/02/1996	5.0	5	130	17			3	01/
114.5	0,00		70	130	-	390	i	50	< >
HA-5	06/02/1996	5.0	=======================================	>>	5	ç			AT.
			2.5	77	7	25	-	7.7	۱,


NOTES: '--- - Parameter not analyzed.


ND - Not Detected above the laboratory Method Detection Limit.

Bolded concentrations are above NR 720 Residual Contaminant Level









Downstream - Safety, Health & Environment Environmental Remediation

Certified Mail # 7002 0510 0000 2287 9553

ExconMobil

October 25, 2002

Refining & Supply

Mr. Rashinder Lal and Harshinder Bhatia 3800 West Hampton Avenue Milwaukee, WI 53209

Re: GIS Registry

Former Mobil Service Station No. 05-PEV 3800 West Hampton Avenue Milwaukee, Wisconsin

Dear Mr. Lal and Mr. Bhatia:

I am writing to notify you of revisions to the NR 700 rule series of the Wisconsin Administrative Code (WAC). Changes to the WAC became effective November 1, 2001 requiring certain properties to be listed on a geographic information system (GIS) Registry maintained by the Wisconsin Department of Natural Resources (WDNR). This rule change allows for closure of environmental remediation sites where natural attenuation is being used to complete groundwater cleanup without requiring groundwater use restrictions to be recorded with the property ceed.

Groundwater at the property identified as 3800 West Hampton Avenue, Milwaukee, Wisconsin (the Property) has been tested by ExxonMobil's consultants on a frequent basis, and has exhibited levels of benzene and methyl tert-butyl ether (MTBE) above the state groundwater enforcement standards found in chapter NR 140 of the WAC. However, the environmental consultants who have investigated this property have informed me that the area of dissolved-phase petroleum impacts to groundwater is stable or receding and will naturally degrade over time. Allowing natural attenuation to complete the cleanup at this site will meet the requirements for case closure that are found in chapter NR 726, WAC, and the Wisconsin Department of Commerce (the Department) has determined that no further investigation or remedial action is necessary. A copy of the Department's conditional closure letter for the site, dated April 10, 2000, is included with this letter. Also included is a copy of the WDNR's fact sheet describing the use of natural attenuation as a final remedy (Publication #RR-671).

Since the Department has approved natural attenuation as a remedy for this site, I will be requesting that the Department grant this site final closure. Final closure means that the Department will not be requiring any further investigation or cleanup action to be taken, other than the reliance on natural attenuation.

The Department will not issue a final closure letter for at least 30 days after the date of this letter. As the owner of the Property, you may contact the Department to provide any technical information that indicates final closure should not be granted for this site. If you would like to submit any information relevant to this final closure request to the Department, you should mail that information to: Ms. Linda Michalets, Hydrogeologist, Wisconsin Department of Commerce, Er vironmental and Regulatory Services Division, 101 West Pleasant Street, Suite 100A, Milwaukee, Wisconsin 53212.

When this case is closed, all properties within the area where groundwater quality exceeds NR 140 groundwater enforcement standards will be listed on the WDNR's GIS Registry of Closed Remediation Sites. The information on the GIS Registry includes maps showing the location of

properties in Wisconsin where groundwater quality above chapter NR 140 standards was found at the time that the case was closed. This GIS Registry will be available to the general public on the WDNR's internal web site. I have enclosed with this letter the legal description of the property. Please review this legal description and notify me within the next 30 days if the legal description is incorrect.

The GIS registry will be used by the WDNR to make sure wells are properly installed in Wisconsin. Should you or any subsequent property owner wish to construct or reconstruct a well, special well construction standards may be necessary to protect the well from groundwater above NR 140 enforcement standards. Any well driller who proposes to construct a well on the Property in the future will first need to call the Digger's Hotline (1-800-242-8511) if the Property is located outside of the service area of a municipally owned water system. If the Property is located within the designated service area of a municipally owned water system, the driller will need to contact the Drinking Water program within the WDNR. Either way, the WDNR will then contact the well driller to advise if there is a need for special well construction standards.

It is my understanding that the Property was purchased from Mobil Oil Corporation during December 1994. Neither you nor any subsequent owner of the Property will be held responsible for investigation or cleanup of impacts to groundwater caused by activities that occurred at the property prior to 1994, as long as you and any subsequent owners comply with the requirement of section 292.13, Wisconsin Statutes, including allowing access to you property for environmental investigation or cleanup if access is required. For further information on the requirements of Section 292.13, Wisconsin Statutes, you may call 1-800-367-6076 to obtain a copy of the WDNR's publication #RR-589, Fact Sheet 10: Guidance for Dealing with Properties Affected by Off-Site Contamination. There are no costs to you for the closure or for the GIS Registry.

Once the Department grants final closure, it will be documented in a letter. I will forward you a copy of the closure letter for your information. You may also obtain a copy of this letter by writing to the agency address given above, or by accessing the DNR GIS Registry of Closed Remediation Sites on the internet at www.dnr.state.wi.us/org/at/et/geo/gwur. A copy of the closure letter will be included as part of the site file on the GIS Registry of Closed Remediation Sites.

Should you have any questions regarding this correspondence, please dc not hesitate to contact me at (815) 521-7369, or you may contact Ms. Linda Michalets of the Wisconsin Department of Commerce at (414)-220-5376.

Sincerely,

Territory Manager

ExxonMobil Oil Corporation

Attachments:

- 1. Conditional Closure Letter (April 10, 2000)
- 2. WDNR Factsheet (Publication #RR-671)
- 3. Legal Description of the Property

cc: Tammi Nagel, Handex of Wisconsin

Linda Michalets, Wisconsin Department of Commerce



Certified Mail # 7002 0510 0000 2287 9430

November 27, 2002

City Clerk City of Milwaukee 200 East Wells Milwaukee, Wisconsin 53203

Re: Notification of Potential Petroleum Impacts within ROW Adjacent to:

Mobil Service Station 05-PEV 3800 West Hampton Avenue Milwaukee, Wisconsin Commerce #53209-5326-00

Dear Sir or Madam:

Handex of Wisconsin (Handex) has prepared this letter on behalf of ExxonMobil Refining and Supply Company (ExxonMobil) to notify the City of Milwaukee (the City) that residual petroleum impacts to groundwater may be present within the West Hampton right-of-way (ROW) located adjacent to the above-referenced property. This notification is required by the State of Wisconsin as a condition of final closure for the environmental case file associated with the service station.

In a letter dated April 10, 2000, the Wisconsin Department of Commerce (COMM - Environmental and Regulatory Services) granted conditional closure of the environmental case file opened for the referenced property in 1991. In the April 2000 letter COMM states that "no further investigation or remedial action is necessary" for the service station. Although COMM has determined that no further action is necessary at the site, residual groundwater impacts may be present within the West Hampton Avenue ROW located adjacent and south of the service station.

As of August 1999, methyl tert-butyl ether (MTBE) was reported at a concentration of 200 micrograms per liter (μ g/L) in a monitoring well (MW-3) located north of the West Hampton Avenue ROW. A site map with groundwater concentrations is included for your reference.

Should you have any questions, or require additional information, please feel free to contact the undersigned in writing at the letterhead address, or by telephone at (262) 641-9011, extension 110.

Sincerely,

Handex of Wisconsin

Tammi L. Nagel Project Manager

cc: Jeff Johnson, ExxonMobil Refining and Supply Company

Gary Mick, Milwaukee County (DPW) (Certified Mail 7002 0510 0000 2287 9423)

Keith Ponath, Milwaukee County (Highway Operations)